

Photo 1 – Ryan Farm (Howrigan & Sons), 1012 South Rd., Fairfield, VT – 08/02/16  
Concrete heifer barnyard.



Photo 2 – Ryan Farm (Howrigan & Sons), 1012 South Rd., Fairfield, VT – 08/02/16  
Location where manure leaks from the concrete heifer barnyard.



Photo 3 – Ryan Farm (Howrigan & Sons), 1012 South Rd., Fairfield, VT – 08/02/16  
Manure solids and liquid from the heifer barnyard in the silage collection system VTA.



Photo 4 – Sheldon Farm (Howrigan & Sons), 429 Northrop Rd., Sheldon, VT – 08/02/16  
Silage bunkers at Sheldon Farm.



Photo 5 – Sheldon Farm (Howrigan & Sons), 429 Northrop Rd., Sheldon, VT – 08/02/16  
Leachate pooled on the back side of the silage piles.



Photo 6 – Sheldon Farm (Howrigan & Sons), 429 Northrop Rd., Sheldon, VT – 08/02/16  
Open dirt lot (formerly a ditch) which receives high flow runoff from the silage collection system.




Photo 7 – Sheldon Farm (Howrigan & Sons), 429 Northrop Rd., Sheldon, VT – 08/02/16  
Concrete walkway for milking cows.



Photo 8 – Sheldon Farm (Howrigan & Sons), 429 Northrop Rd., Sheldon, VT – 08/02/16  
Manure seeping through a break in the concrete walkway curbing.



Photo 9 – Home Farm (Howrigan & Sons), 104 Rd., Sheldon, VT – 08/02/16  
Location where silage runoff is directed into a storage pond.